


T908C

◆ 安装尺寸/Mounting Dimension



◆ 参数

Specifications


技术指标/Technique

额定容量	Capacity	0.1,0.2,0.3,0.5, 1,2,3,5Nm
输出灵敏度	Sensitivity	1.0~1.5mV/V
零点输出	Zero balance	± 1% F.S.
非线性	Non-linearity	0.2%F.S.
滞后	Hysteresis	0.2%F.S.
重复性	Repeatability	0.1%F.S.
蠕变 (30min)	Creep(30min)	0.2%F.S.
温度灵敏度漂移	Temp.effect on sensitivity	0.1%F.S./10°C
零点温度漂移	Temp.effect on zero	0.1%F.S./10°C
输入电阻	Input impedance	350 ± 10 Ω
输出电阻	Output impedance	350 ± 10 Ω
绝缘电阻	Insulation	≥2000M Ω/100VDC
激励电压	Recommended excitation	12V
最大激励电压	Maximum excitation Voltage	20V
温度补偿范围	Compensated temp range	-10~60°C
工作温度范围	Operating temperature range	-30~60°C
安全载荷	Safe load limit	120%F.S.
破坏负载	Breaking load	150%F.S.
电缆线尺寸	Cable size	3m
防护等级	IP Class	IP66

◆ 特点与用途/Features & Applications

- 电阻应变为敏感元件和集成电路构成的一体产品;
- 精度高，性能稳定可靠;
- 电刷供电,可测量正反两方向扭矩值;
- 两端均为键连接,安装使用方便;
- 最高测量转速4000转/分钟。
- The resistance strain is an integrated product consisting of sensitive components and integrated circuits;
- High accuracy, stable and reliable performance;
- Brush power supply, can measure the positive and negative two direction torque value;
- The two ends are connected by keys, and the installation and use are convenient;
- The highest measuring speed is 4000 revolutions per minute.

◆ 配线图/ Wiring Code



新产品

压向传感器

拉压向传感器

压电传感器

多维力传感器

称重传感器

张力传感器

螺纹力

扭矩传感器

其它定制力传感器

称重模块

仪表模块放大器